مشخصات فنی عمومی شیشه کاری درساختمان



این نشریه پیش نویس مشخصات فنی عمومی شیشه کاری در ساختمان میباشد و ششمین نشریه است که درزمینه مشخصات فنی عمومی کارها ی ساختمان با استفاده از خدمات مهندسان مشاور تکنولوگ به دو زبسان فارسی و انگلیسی تهیه شده است .

اینك ضمن قدردانی از زحمات كارشناسان موسسه مذكور این نشسریسه دراختیار دستگاههای اجرائی و مهند سان مشاور قرار میگیرد .

امیداست متخصصین فن با مطالعه این مشخصات نظریات اصلاحی خود را ابراز دارند که درتهیه متن نهائی مورد استفاده قرار گیرد.

د فترتحقيقات واستاند ارد هاى فني



فهسرست مند رجسات

قسمت اول ــ مقررات کلی برای کارهای شیشه کـاری

		رد پـــف
9	دامنه کـــار	1-1
1	استاند ارد ها وآثین ناهها	7—1
الى ٢	نمونسه وآزما يسش	r-1
۲	ارجحيست	{1
٣	بازرسىي	0—1
	ه کــــاری	قسمت دوم ــ مصالح شيش
for	كليسات	7—1
۱۳ لی ۶	<u>مــــ</u>	7—7
Ę	موادلازم برای نصب شیشیه	٣٢
•	ملحقسات	{ ······ ٢
٥	نمونسه	0—7
مالی چ	انبارنمودن وحمل ونقسل	7—7
	شیشه کـاری	قسمت سوم _ نصب مصالح
۱۷لی ۸	کارهای مقدماتی شیشه کاری	1-5
۱۰ ۱۸	نصب قسمتهای مختلف شیشه کاری	r-r



قسمت چہارم ـ بازرسی وقبول کارهای شیشه کـاری

مفحـــه		رد يــــف	
11	بازرسىسى	1-1	
11	شستن وتميزكارى	3-7	
7.1	قبول کــرد ن	7-8	



قسمت اول

مقررات کلی برایکارهای شیشهکاری

۱-۱ دامنه کسار

کارهای شیشه کاری شامل تهیه کارگر، مصالح ، وسائل و ستگاههها انجام کلیه کارهای لازم برای اجرای کامل کارهای شیشه کاری برطبسق نقشهها ومقررات اسناد قرارد اد بارضایت کامل د ستگاه نظارت میباشد .

١-- ١ استاند ارد ها وآئين نا مه هـا

کلیه مصالح باید مطابق استاند ارد های مربوطه ایران وهمچنین سایسر ملزومات مندرج دراین مشخضات فنی عمومی باشد مصالحی کسه برای آن استاند ارد ایرانی تهیه نشده ویامصالحی که دراین مشخصات فنی عمومی ذکرنشده اند باید مطابق بااستاند ارد های بین المللسی مورد قبول د ستگاه نظارت باشد .

۱_۳ نمونه وآزمایـش

الف ـ كليه مصالح وكارهامشمول آزمايشات مندرج دراين مشخصات فنسس عموس وياآزمايشات خواسته شده د يگرازطرف د ستگاه نظارت خواهسد .

ب د رصورت د رخواست د ستگاه نظارت ، پیمانکارموظف است بهزینه خسود وقبل از شروع کارتعد اد کافی نمونه برای تصویب د راختیار د ستگاه نظارت قرارد هد واسناد ود لایل کافی نسبت به مناسب بودن مصالح و مرغوبیست کارارائه نماید .

مقررات كلىبراى كارهاى شيشهكارى

ج سه مصالح حمل شده بکارگاه که بهرعتوان نامرغوب ترازنمونههای مسورد تصویب باشند ویابرطبق مشخصات نباشند مرد ود شناخته شده وبایسد ازمحوطه کارگاه خارج شوند .

1-٤ ارجعيــــت

الف ـ هرگاه بین مندرجات این مشخصات فنی ـ عمومی ونقشه های مربوطـه تناقضی دیده شود ارجحیت آن مطابق مفاد ماده ۲ پیمان بانقشه هـا خواهد بود .

١- م بازرسي

پیمانکارموظف است که تسهیلات لازم راجهت بازدید دستگاه نظـــارت درکلیه اوقات ازکارگاهها ، انبارها ، ومحل کارفراهم نماید . فراهــــم آوردن اینگونه تسهیلات توسط پیمانکاربهیچوجه از مسئولیت اود ر مسورد ارا که مصالح مرغوب نخواهد کاست .

قسمست د وم

مصالح شیشه کـــاری

١-٢ كليسات

کلیه مصالح شیشه کاری ذکرشده دراین مشخصات فنی عمومی که برای تکمیل شیشه کاری لازم میباشند باید نو بوده و ازنقطه نظرنوع ، مرغوبیت، پرداخت ، رنگ ، عملکرد و مقاومت بتصویب دستگاه نظارت برسند .

۲-۲ شیشیه

- الف بیمانکارباید نمونه های شیشه را طبق بند ه ۱ این مشخصات فنی تعمومی برای تصویب بدستگاه نظارت تحویل د هدو سپس از روی نمونه های تصویب شده برای کل مقد ارشیشه که برای تکمیل شیشه کاری لازم است سفارش د هد .
- ب برچسب کمپانی سازنده باید تاتمیزکاری نهائی برروی شیشه هائی که مورد تصویب دستگاه نظارت قرارگرفته است باقی بماند .
- ج شیشه شفاف باید بصورت ورقهائی بضخاست حد اقل ه / ۲ میلیمتر و عاری از موج ، حبابهای هوای بزرگتر ازیك میلیمتر و سایرنقاعص باشد. ضخامت و رنگ شیشه باید درتمامی سطح یکنواخت باشد .
- د _ شیشه با مقاومت زیاد باید ازورقهائی بضخامت ؟ میلیمتر باحد اکث ان حد اقل ۱۰ کندراف مجاز ۲/۰ ± میلیمتر ساخته شده باشد و وزن آن حد اقل ۱۰ کیلوگرم درمترمربع باشد .
- هـ شیشه مات باید شیشه بدون پرداخت و بضخامت حداقل عمیلیمترونیمه

شفاف بارنگ یکد ست باشد ویك سطح آن صاف وسطح دیگرزبروصیقل نشده باشد و درصورت لزوم برای ایجاد ماتی لا زم شن پاشی گردد.

- و سشیه مسلح (سیمدار) باید دارای ضخامتی حداقل برابربا ۲ میلیمتر باشد . شیکه سیمی بکاررفته بایدیا از سیم تابید ه بمقطع شش ضلمی با چشمه های تقریبا" (۲۲×۲۲) میلیمتری ویا شبکه لحیم شده با سیمهای لوزی شکل به اقطار (۲۱×۲۲) میلیمتری باشد د ورتا د ورلبه های شیشه بعرض یك سانتیمترباید فاقد شبکه سیمی باشد .
- ز س شیشه مخصوص ازقبیل شیشه مقاوم درمقابل حرارت یاشیشه جسانی حرارت باید ازسازنده مورد تصویب وطبق مشخصات تعیین شده بوسیله دستگاه نظارت تهیه گردد.

۲-۳ مواد لازم براى نصب شيشه.

- الف _ مصالح انعطاف پذیر از قبیل بطانه باید از بهترین نوع ومناسب برای فلز قاب شیشه باشد .
- ب م<u>صالح انعطافنا پذیر</u> ازقبیل زه فلزی یا چوبی د ورشیشه که بجای بطانه برای نگاهد اشتن شیشه بکارمیرود و همراه باد روپنجره ارسال میگرد د باید برای کارگذاشتن شیشه برد اشته شده و د ومرتبه کارگذاشته شود .

٢_} ملحقيات

کلیه مصالح لازم ازقبیل گوه ، گیره نصب شیشه ، آلات محکم نمودن شیشه ، نمد وغیره که دربالا ذکرنشده است ولی برای نصب کامل وقابل قبول شیشه لازم است باید تهیه هگردد .

۲_ه نمونــه

- الف ـ کلیه مصالح وموادی که برای کارهای شیشه کاری تحویل دادهمیشود باید ازهرلحاظ بانمونههای تصویب شده مطابقت نمایند .
 - ب یمانکار باید نمونه های زیل رابرای تصریب به د ستگاه نظارت تحویل د هدد .

ا شیشه

- دونمونه ازهرنوع شیشه که درشیشه کاری باید بکسار رود .
- هیچیك ازنمونه هانباید كوچكتراز . . عسانتیمترمربیع (۲۰ cm×۲۰cm) باشید .
- هریای ازنمونه هاباید بوسیله برچسبی که نمود ارندوی، مرغوبیت، محل نصب درساختمان ونام کارخانه سازنده آن است مشخص شده باشد .

۲_ مواد قابل انعطاف برای نصب شیشه

- یک قوطی باشیشه حاوی یک چهارم (ایم) کیلوگررم ازمصالح قابل انعطاف که برای شیشه کاری درنظر گرفته شده است .
- چهار (۶)کیی ازد ستورالعمل کارخانه سازنده ایسن
 مصالح شیشه کاری د رمورد کاربرد آن

٦-٢ انبارنمودن وحمل ونقل شيشه

الف_د رهنگام انبارنمودن ورقهای شیشه باید بین آنهایك لایه از كافدن

- قسرارداد .
- ب سیشه ها باید همگی اعم ازاینکه درجعبه های چوبی ویابه ورت دیگری بسته بندی گردند عاری ازرطوبت نگهداشته شوند .
- ج بمنظورجلوگیری ازپریدن لبه شیشه هاویاخراش برداشتن بسیل وارد آمدن سایرخسارات به شیشه هاباید آنهاراباد قت ازجمبهها خارج نمسود .
- د به ورقهای شیشه راباید بصورت قائم بلند نمود ه وآنهاراد رد ستههائی که تمداد آنهانباید بیش ازه ۲عد د باشد د رامتد اد طولشان د رروی ۲ تیرچوبی که هریک ۳۰سانتیمترازد ولیه شیشه هافاصله د ارنسد قرارد اد .
- ه _ ورقهای شیشه راباید بنحوی روی تیرهای چوبی قرارد اد وبه حائل عمودی تکیه داد که ازلفزش پوارد آمدن هرنوع آسیب بآنه____ا حلوگیری شـود .
- و ـ شیشه های یا دسته بایدحتی المقد ورنزدیك بهم وقائم قــرار داده شوند.

فسمست سسسوم

نصب مصالح شیشه کاری

۱–۳ کارهای مقدماتی شیشه کـاری

الف _ د روپنجــره

- ۱ کارهای شیشه کاریباید پس ازاتمام کارهای اندود کاری دیوارها (داخلی وخارجی)ولی قبل ازشروع کارهای نقاشی (رنگ آمیزی) وکت سازی (کاشیکاری وغیره)انجام گیسرد.
- ۲ قبل ازکار گذاشتن مصالح شیشه کاری باید درفرورفتگیها و شکافهای دروپنجره هاکه احتیاج بهبطانه کاری دا رند ابتد ایك آسترروفنسی مالید وسپس برای زدودن ناخالصبها و براده های زنگ زدگی آنها را بابرس تمیزکسرد.
- ۳- قبل ازشروع عملیات شیشه کاری بهتراست یك قشررنگ برروی درها و پنجرههای فلزی مالیده شود .

ب ــ سقــــن

- ۱- درسقفهای شیبداری که نورازطرف یك شیب وارد میشود (ازقبیسل سقفهائی که فقط شیب طرف شمال نورگیردارد)برای جلوگیسری ازخسارت بادبه شیشه درهنگام نصب باید ابتد اورق سقف پسوش طرف بدون نورگیرکارگذاشته شسود .
- ۲- قبل ازشروع کارهای شیشه کاری باید کارهای نصب کلیه ورقه سیای سقف پوش د رزیروا طراف قسمت شیشه کاری تمام شده وآبروها نصب گردیده باشند وکلیه د رزدابند کشی شده وکارهای مقد ماتی بسیرای

نصب ورق آب بندی د را طراف شیشه کاری انجام گردیده باشد .

- د رروی سطحی که ورق پوششی ونورگیرد ارد شیشه کاربرای آنکه اطراف شیشه رابا ورق آببندی بپوشاند باید بلافاصله پس از آنکه ورقهای پوششی زیرشیشه هانصب گردید کارخود را شروع نماید .

ورقهای بالای شیشه هانباید تاقبل از آنکه شیشه ها وورق آب بندی بالانصب گردیده اند کارگذاشته شهود .

ج - مصالح شیشه کاری

- ۱- شیشه باید درمحوطه کاربرروی نیمکت مخصوص کاربه ابعاد دو (۲)
 یاسه (۳) میلیمترکوچکترازابهاد اند ازهگرفته شد هقالب دروپنجرههابریده شود . اند ازه های شیشه ها که درنقشه ها ذکرشد ه اند فقلل اند ازه های تقریبی است وابعاد صحیح شیشه هاباید بااند ازه گرفتن تمام قابهای که شیشه درآنها کارگذاشته میشود بد سست
 - ۲- شیشه هائی که درنقشه هامشخص نگردید هاند باید ازنوع مشابسه شیشه هائی باشد که درمحلهای مشابه درقسمتهای دریگرپسروژه بناررفته اند .

۲-۳ نصب قسمتهای مختلف شیشه کاری

الف _ كليسات

- ۱- قاب باید قبل ازشروع کارهای نصب شیشه تمیزوخشك باشد .
- ۲- درموارد یکه سطوح شیشه متفاوت هستند برای جلوگیری از جمسیع شدن خاك برروی شیشه سطح صافترباید بطرف بیرون باشد .
- ۳ جزد رموارد یکه درنقشه هاذ کرشده باشد شیشه های توالته میسا،

حمام هاورختکن هاباید مات باشند ، برای در هاوپنجهها ، درو درقابها نیکه بیشترازیک مترمربع وسعت دارند وبرای کلیه درو پنجرههای فولادی وآلومینیوس که سراسرشیشه دارند باید شیشه مخصوص با مقاومت مضاعف بکاربهرد .

- ٤- شیشه باید طوری بریده شود که کاملا باند ازه شیار قایبا شید.
 بطوریکه حد اکثر فاصله سطح شیشه ازدیواره شیار ۲میلیمترباشد .
- ه پس ازاینکه شیشه درشیارنشانده شد ،بایدبطانه بادقیت لازمدر امتد اد کناره هامالیده شود ومقد اراضافه درجریان پیشرفیت بطانه کاری زدائیده شیود .
- 7- زه اطراف قابهاباید باد قت کامل د رجلوگیری ازوارد شدن هرگونه خراش ولطمه ازجاد رآور ده شده ود ومرتبه پس ازانجام کارهای لا زم نصب گـرد د .
- ۷- تفاوت ابما دعرض وارتفاع قابهای شیارد اروشیشه ها که درآنهاکسار
 گذاشته میشوند نباید کلا" از ۲ میلیمتر تجاوزنماید وشیشه بایسد در
 د اخل قاب طوری میزان شود که فشارا تکا ۲ آن برهرچهارلبسسه
 یکنواخت باشد .

ب _ مهارکردن بابطانه

۱- ابتد اباید قشری بضخامت دو (۲) میلیمتراز بطانعتشکل ازروغ اروغ برزك وگئ ویاسایرمواد قابل انعظاف مورد قبول ومناسب بسرای شیشه کاری درامتد اد شیارقاب مالیده گرد د وسپس صفحه شیشه که باند ازه صحیح بریده شده است بوسیله د ست بافشارلا زم بطوریک کاملا" بمطانه بچسبد درد اخل شیارکارگذاشته شود .

٢- سپس صفحه شيشه بايد بطرق زيرمحكم گـردد:

- (الف) د رمورد د روپنجره های فولادی وآلومینیوس بوسیلیده گیره های مخصوص که بوسیله کارخانجات سازنیدده د روپنجره فولادی وآلومینیوس تحویل داده میشود.
- (ب) میخهای مخصوص با سراستوانه ای شکل ویاپیچهای چوبسی سرپهن برای درها و پنجره های چوبی .

ج ۔ مہارکردن با زہ

- ۱- ابتداشیشه که باندازه صحیح بریده شده است باید درقشـــری بضخامت دو (۲) میلیمترازبطانهمناسب که مانع انقبانی وانبسـاط شیشه نگرد د کارگذاشته شـود .
 - ۲ سپس صفحه شیشه باید بوسایل مذکورد رذیل مهارگرد د .
 - (الف) برای د روپنجره چوبی «بوسیله زه چوبی که بوسیله پیه نصب گردد.
 - (ب) برای د روپنجره فولا دی ، بوسیله زه فولا دی که بوسیله می پیچ نصب گـرد د .

قسمت چهارم

بازرسی وقبول کارهای شیشه کـــاری

۱-۱ بازرســـی

- الف ــ پیمانکار باید تسهیلات لازم را برای بازرسی کارها چه درهنگام انجام وچه پساز اتمام کار دراختیار دستگاه نظارت قرارد هد .
 - ب ــ شیشه نباید ترك داشته باشد
- ج ــ لکه های رنگ وسایر لکه ها باید از روی شیشه وقاب پنجره زدوده شود و شیشه شسته وتمیز گردد.
 - د ـ زه وبطانه باید کاملا" باشیشه تماس داشته باشند و دورآنرا بگیرند .


٢-١ شستن وتميز كارى

- الف ــ پس از آنکه شیشه کاری بازرسی گردیده ومورد قبول واقع گردید پیمانگار باید مرد وسطح شیشه را دقیقا" شسته ، تمیز کرده وصیقل دهد .
- ب ـ درتمیز کردن شیشه باید دقت کافی بعمل آید تالطمهای به زه ، بطانه ویا ورق آب بندی وارد نیاید .
- ج ـ کلیه زوایای قاب دروپنجرهها ،گوشه شیشهها ولبه های قاب درو پنجرهها بره سیشهها ولبه های قاب درو پنجرهها بره سید تمیز گردند .
- د یمانکار مجاز نیست که برای تمیز کاری مواد اسیدی وبازی قوی بکارببرد .
 درمواردیکه کتافات با طرق عادی تمیز نمیگرد دپیمانکار باید اسید ویسا
 باز مصرفی را به تائید دستگاه نظارت برساند .

بازرسى وقبول كارهاى شيشه كارى

٤ ٣-٤ قبول كرد ن

الف شیشه باید درمقابل صدمه وخسارت محافظت گرد دوشیشه هائی کسه قبل از تحویل ومورد قبول واقع شدن صدمه دیده است باید عوض گرد د. ب درصورتیکه دستگاه نظارت لازم بداند باید برای جلوگیری از لسرزش وشکستن شیشه گیره های مهار ضد طوفان برای شیشه ها تعبیه گرد د.





INSPECTION AND ACCEPTANCE OF GLAZING

alkalies for cleaning. He shall get the approval of the Engineer for use of such acids and/or alkalies, where dirt cannot be removed by normal methods.

4.3 ACCEPTANCE

- a. Glass shall be protected against damage, and glass damaged before the final acceptance of the work shall be replaced.
- b. Storm clips shall be provided to prevent rattling and breaking of the pane if the Engineer so requires.

SECTION 4

INSPECTION AND ACCEPTANCE OF GLAZING

4.1 INSPECTION

- a. The contractor shall provide all facilities for the Engineer for inspection of the work while it is in progress and after its completion.
- b. The glass shall mot be cracked.
- c. Paint smears and soot on the glass and sash shall be removed and the glass shall be washed clean.
- d. Beads and putty cushions shall make close contact with the glass.

4.2 WASHING AND CLEANING

- a. After all glass has been inspected and approved, the Contractor shall thoroughly wash, clean and polish the glazing on both surfaces.
- b. In cleaning the glass care shall be taken not to disturb the beads, putty or flashing.
- c. All corners of sash frame angles of glass and along sash edges shall be carefully cleaned.
- d. The Contractor shall not use strong acids and

- 2. Then the pane shall be secured by:
 - (a) Glazing clips, for steel and aluminium doors and windows, supplied by the steel or aluminium sash manufacturer.
 - (b) Cylinder headed nails or flush headed wood screws for wooden doors and windows.
- 3. The rabbet shall be completely filled with putty and cut off smoothly at a 45 degree angle with mitred angles.

c. Glazing with Beads or Stops

- The cut-to-size glass is bedded firmly in a two
 (2) mm. thick layer putty or other approved
 cushion (glazing compound) that will permit
 normal expansion and contraction.
- 2. Then the pane shall be secured by:
 - (a) Glazing heads of wood, for wooden doors and windows, fixed by screws.
 - (b) Glazing beads of steel, for steel doors and windows, fixed by screws.

- 3. Unless otherwise shown on Drawings, glass for toilets, showers and lockers shall be obscure glass. Double-strength glass shall be used for window and door panes larger than one (1) square meter in area and for all glazed steel and aluminium doors.
- 4. All glass shall be cut to completely fill the rabbets with a 2 mm. maximum clearance.
- 5. After the glass has been fixed, the putty shall be neatly run in straight lines and even with edges of sash members, and all surplus material removed from glass as work progresses.
- 6. Glazing beads shall be carefully removed and reset, using every precaution to avoid marking or defacing.
- 7. The difference between width or height of rabbetted opening and corresponding dimensions of glass shall not exceed 6mm. overall and the glass shall be so centered in the opening as to provide uniform bearing on all four edges.

b. Glazing with Putty

1. About two (2) mm thick layer of putty composed of linseed oil and chalk putty or other approved ed elastic glazing compound is applied along the puttying groove or rabbet before the cutto-size glass is placed by hand and pressed so as to completely stick to the putty.

3. On a sheeted and glazed roof slope, the glazier shall begin his work as soon as the sheets below the glass are fixed, so that he may dress down the flashing on to the sheets. The sheets above the glass shall not be laid until the glazier has fixed the glazing and laid the top flashing.

c. Glazing Materials

- 1. Glass shall be site-cut, on a work bench, two
 (2) to three (3) mm. smaller than the measured
 dimension of doors and window panes. The size
 of glass shown on the Drawings are approximate,
 and the actual sizes shall be determined by
 measuring all frames to receive glass.
- Glass required and not specifically mentioned or described on the Drawings shall be same as indicated for other similar or corresponding locations.

3.2 FIXING GLAZING PARTS

a. General

- Sash shall be clean and dry before glazing.
- 2. Where the two surfaces of glass differ, it shall be laid with the smooth surface outermost to minimize the collection of dirt on the rougher surface.

SECTION 3

INSTALLATION OF GLAZING

3.1 PREPARATION FOR GLAZING

a. Doors and Windows

- Glazing shall start after completion of plastering of walls (internal and external) but before painting and flooring work (tiling, etc.).
- 2. Grooves in doors and windows, to be puttied, shall be first coated with an oil primer and cleaned by brushing to remove impurities and rust traces before applying the glazing compound.
- 3. It is recommended to apply a coat of paint on metal doors and windows before glazing operations are started.

b. Roofs

- In roofs glazed on one slope only (e.g. northlight roofs), the covering on the unglazed slope shall be fixed in advance of glazing to prevent glass from being disturbed by strong winds.
- 2. All roofing below and at the ends of glazing shall be completed and all gutters fixed before glazing is commenced; joints shall be raked out, and all preparations made as required to take the flashing to the glass.

Four (4) copies of the glazing compound manufacturer's printed directions for their application.

2.6 STORAGE AND HANDLING

a. Glass

- Sheets or glass shall be stored with a layer of paper separating them.
- 2. All glass shall be kept dry whether stored in crates or packed otherwise.
- 3. Glass shall be removed from the crates carefully to avoid edge chipping, scratching and other damages.
- 4. The glass shall be lifted and stored on its long edge and shall be put into stacks of not more than 25 panes, supported at two points by fillets of wood at about 30 cm. from each end.
- 5. A stack of panes shall be laid on wooden fillets and rested against the vertical support in such a manner that it shall be prevented from sliding or any changes during storage.
- 6. The whole stack shall be as closely packed and as upright as possible.

clips, securement devices, felt, etc., not specifically referenced above but required to provide a complete, satisfactory and approved installation shall be furnished.

2.5 SAMPLES

a. General

- Materials, delivered to be used in glazing work, shall conform, in every respect, to the approved samples.
- 2. The Contractor shall submit to the Engineer the following samples for his approval:-

(a) Glass

- Two samples of every type of glass to be used.
- Each sample shall be not less than 400 sq.cm.(20cm.:: 20cm.) in size.
- All samples shall be identified by a label indicating the kind, quality, the name of the manufacturer and the location in the project where they should be installed.

(b) Elastic Glazing Compound

- A container containing a sample of one quarter (%) kg. of glazing compound to be used.

- e. Obscure-Glass shall be rough-cast glass of a minimum 4 mm thickness and shall be translucent, without color tinting and smooth on one side. The other surface shall be unpolished and light sandblasted if necessary to provide obscuration.
- f. Wired-Glass shall be a minimum 6 mm thick. The wire used shall be either in the form of a twisted hexagonal mesh with openings approximately (32x22) mm or a welded diamond mesh with openings (29x16) mm. One (1) cm. non-reinforced edge shall be allowed all around.
- g. Special-Glass such as heat-resisting, and heatabsorbing glass shall be from approved manufacturers and to the Engineer's specifications.

2.3 GLAZING COMPOUNDS

- a. Elastic Material such as putty shall be the best available and shall be suitable for the metal of the sash.
- b. <u>Mon-elastic Material</u> such as metal and wooden glazing beads when furnished with the doors and windows, shall be removed for glazing and reset by the Contractor.

2.4 FITTINGS

a. All incidental materials such as shims, glazing

SECTION 2

MATERIALS FOR GLAZING

2.1 GENERAL

a. Materials specified hereinafter and required to complete glazing work shall be subject to the Engineer's approval at all times as to the kind, quality, finish, color, function and strength, and shall be new.

2.2 GLASS

- a. The Contractor shall submit samples of glass according to paragraph 2.5, of this specification to the Engineer, and in accordance with the approved samples he shall place an order for all glass he intends to use for glazing work.
- b. Labels shall remain on the glass checked and approved by the Engineer until the final clean up.
- c. Clear Glass shall be sheet type, not less than 2.5 mm thick, free from distortions, air bubbles larger than 1 mm, and other defects. Thickness and color shall be uniform throughout.
- d. <u>Double-Strength Glass</u>: Shall be sheet glass of minimum 4 mm thickness, with a maximum thickness tolerance of ±0.2 mm. It shall weigh at least 10 kg. per square meter.

GENERAL REQUIREMENTS FOR DOORS AND WINDOWS

- b. The Contractor shall, before proceeding with the works and at his own expense, furnish for approval sufficient quantities of samples or other satisfactory evidence as to the kind and quality of marterials and workmanship, when so required by the Engineer.
- c. Material delivered to the Site which are in any way inferior to the approved samples and/or fail to meet the relevant requirements shall be rejected and removed from the Site.

1.4 PREVALENCE OF DOCUMENTS

Where the Contract Drawings and the clauses of this specification contradict, the contractor drawings are prevail.

1.5 INSPECTION

a. The Engineer shall have free access, at all reasonable times, to inspect the materials in the mill, stockyard, shop and field, however, this shall not relieve the Contractor of his responsibilities to furnish satisfactory materials.

SECTION 1

GENERAL REQUIREMENTS FOR GLAZING

1.1 SCOPE OF WORK

a. Glazing shall include the provision of all labour, materials, equipments and services, and the performance of all operations required for the complete execution of all works as specified herein and/or indicated on the Drawings, in accordance with the requirements of the Contract Documents and to the complete satisfaction of the Engineer.

1.2 STANDARDS AND CODES

a. All materials shall meet the requirements of the respective Iranian Standards (I.S.I.R.I.) and such additional requirements as specified herein. The materials which have not been covered in these specifications and for which no Iranian Standards have been prepared shall meet the requirements of such International Standards and Codes as approved by the Engineer.

1.3 SAMPLES AND TESTS

a. All materials and workmanship shall be subjected to the test(s) indicated hereinafter and/or any additional test(s) as may be required by the Engineer.

			'-
	•		
			:
			•
			٦
			1
			7

CONTENT

SECTION 1 - GENERAL REQUIREMENTS FOR GLAZING

PARAGRAPH	DESCRIPTION	PAGE NO.
1.1 1.2 1.3 1.4 1.5	Scope of Work Standards and Codes Samples amd Tests Prevalence of Documents Inspection	1-1 1-1 to 1-2 1-2 1-2
SECTION 2 -	MATERIALS FOR GLAZING	
2.1 2.2 2.3 2.4 2.5 2.6	General Glass Glazing Compounds Fittings Samples Storage and Handling INSTALLATION OF GLAZING	2-2 2-1 to 2-2 2-2 2-2 to 2-3 2-3 to 2-4 2-4
3.1 3.2	Preparation for Glazing Fixing Glazing Parts	3-1 to 3-2 3-2 to 3-4
SECTION 4 -	INSPECTION AND ACCEPTANCE OF	GLAZING
4.1 4.2 4.3	Inspection Washing and Cleaning Acceptance	4-1 4-1 to 4-2 4-2

. .

~;

GENERAL - TECHNICAL SPECIFICATION OF GLAZING